November 23,.2009 • 11:24:57 AM

D

Item ID:

D2596

Accept

Setup Start



Stop



**Revision ID:** 

Web, 205 Skidtube Item Name:

**Start Date:** 

23/11/2009

Start Qty: 4.00

**Required Date: 27/11/2009** Req'd Qty: 4.00



Cust Item ID:

**Customer:** 

Reference:

Approvals:

Sequence ID/

Work Center ID

**Process Plan:** 

Date: 07-11-23 Tooling:

0.00

0.00

Date:

Stop

Start

Date:

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Draw

Number

Plan Reject Reject Insp. Draw Accept Stamp Qty Qty Number Rev. Code

Run

**Draw Nbr Revision Nbr** D2596 Rev D

QC:

100

Skidtubes

Skidtubes

Operation

Description

Memo

1- Cut D2500-3-100 to length: 99.5"  $\Box$ 2- Use Jig DT8093 to drill pilot holes #30 $\Box$ 3- Open to 0.630" diameter as per Dwg D2596 $\Box$ 4- Deburr Skidtubes

HandFinish

Hand Finishing

Chemical Conversion Coat per QSI005 4.1

0.00

Memo

0.00

QC5- Inspect part completeness to step on W/O

oilsilro d

Memo

0.00

Quality Control

Dart Aeros	pace Ltd
------------	----------

										<b>5</b> 2.:
W/O:			V	<b>VORK ORDER CHAN</b>	GES					3 ±
DATE	STEP	PROC	EDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval® QC Inspector
		;								
					:				. 1	A 22 10
Part No:		PAR #:	Fault Ca	tegory:	NCR	: Yes N	o <b>DQA</b>	:	Date: <u>≻</u> _	
		esolution:	A CONTRACTOR OF THE CONTRACTOR							
NCR:		Wo	ORK OR	DER NON-CONFORM	MANCE	(NCR)		,		
DATE	STEP	Description of NC		ection B		Verifica	ation	Approval	Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Sectio		Chief Eng	QC Inspector
	,								and good and	
The state of the s	À. Ge			<u> </u>			ارا معرف الأسرار	- rate		
									<u>.</u>	
·										
				· .	*	. ••		and a survey of the survey of	May safe ( )	porti Notae in prijek
										State of the State
						Ą	1.3			
	]									

NOTE: Date & initial all entries

Item ID:

D2596

Accept

Setup Start

Stop



Revision ID:

**Start Date:** 

D Item Name: · Web, 205 Skidtube

23/11/2009 Start Qty: 4.00

Required Date: 27/11/2009 Req'd Qty: 4.00



**Cust Item ID:** 

Customer:

Reference:

Process Plan

Date:

Tooling:

Run

Start



Approvals:

QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/

Work Center ID

130

Operation Description

Identify as per dwg & Stock Location:

Memo

Set Up/ **Run Hours** 

Draw Number Rev.

Plan. Draw Code

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

Packaging

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

. 0.00

Memo

0.00

Dart A	Aeros	pace	Ltd
--------	-------	------	-----

Dail Ac	Tospace	Lta								•
W/O:		·	V	ORK ORDER CHAN	IGES					*
DATE	STEP	PROC	EDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
						·				
			•	; · · ·						
					3					
<u> </u>					*	:	<u>.</u>			<del> </del>
		•				·				
		•	) }							<b>1</b>
Part No	:	PAR #:	Fault Ca	tegory:	NCF	R: Yes I	No <b>DQ</b>	<b>A</b> :	_ Date: _	
	Re	esolution:	Disposit	on:	QA:	N/C Clo	sed:		Date: _	
NCR:		W	ORK OR	DER NON-CONFORM	MANCE	(NCR	)			
		Description of NC	Corrective Action Section B		ection B	Verification			Ammuoval	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	n	Sign & Date		ion C	Approval Chief Eng	Approva QC Inspecto
	, i									
		•					-			
•										
~										
		•								

NOTE: Date & initial all entries

Picklist Print

November 23, 2009 11:25:02 AM

Work Order ID: 53891

Parent Item: D2596RevD

Parent Item Name: Web, 205 Skidtube

Comments:



Start Date: 23/11/2009

**Required Date: 27/11/2009** 

Page 1

Start Qty: 4.00

Required Qty: 4.00

Component Item ID/	Replacement	Mfg/	.Bin	Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
D2500-3-100RevU/R		Manufactured	No		/3	100 5/95	Each	0.0000	4.0000			

Ext'n - I' Beam Web 4"

Dart Aerospace L	∟td
------------------	-----


W/O:			V	VORK ORDER CHA	NGES					<del> </del>		
<b>DATE</b>	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
·					-	·						
Part No	:	PAR #:	Fault Ca	tegory:	NC	R: Yes	No <b>DQ</b>	<b>4</b> :	Date:	·		
	Re	esolution:	Disposit	ion:	Q <i>A</i>	: N/C CI	N/C Closed: Date:					
NCR:			WORK OR	DER NON-CONFOR	RMANCI	E (NCR	)					
DATE	STEP	Description of NC		Section B		Verific	ation	Approval	Approval			
DAIL	JILF	Section A	Initial Chief Eng	Action Descripti Chief Eng	on	Sign & Date	Secti		Chief Eng	QC Inspector		
									:			
			·			:						
								*				
			-							7 T T T T T T T T T T T T T T T T T T T		
		4										
									•			
		,				1	]					

NOTE: Date & initial all entries



DESIG	RH PH	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAD		
CHECK	KED 11L	APPROVED	DRAWING NO.		V. D
	THE	94	D2596	SHEET 1	
DATE			TITLE	S	CALE
07.0	)4.17		205 WEB		1:20
Α		96.09.16	NEW ISSUE		
В		97.07.23	Ø0.63 HOLE WAS Ø0.56		
С		98.09.14	INCORPORATED DEO 9097		
D		07.04.17	INCORPORATED DEO 9183		

## RELEASED



Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART, AEROSPACE LTD.

